
Assembly Instruction



NO.		QTY	NO.		QTY	NO.		QTY
A		2	В		2	С	\mathbb{R}	3
D	L	3	A1		1	В1		1
Е		1	F		1	G		2
X1	M 6*30	30	X2	() M6*65	6	хз	(M) M6*20	2
Y		38	Z		2			

